

**ACCESORIOS**
**CÓDIGO**
**ROSCA NPT**
**MANGUERA**


|          |      |      |
|----------|------|------|
| N100-10  | 1/8" | 1/4" |
| N100-20  | 1/4" | 1/4" |
| N100-30  | 3/8" | 1/4" |
| N100-40  | 1/4" | 3/8" |
| N100-50  | 3/8" | 3/8" |
| N100-60  | 1/2" | 3/8" |
| N100-70  | 3/8" | 1/2" |
| N100-80  | 1/2" | 1/2" |
| N100-90  | 3/4" | 3/4" |
| N100-100 | 1"   | 1"   |

**TERMINALES MF NPT PARA PRENSAR**
**CÓDIGO**
**ROSCA UNF**
**MANGUERA**


|         |        |      |
|---------|--------|------|
| H100-10 | 7/16"  | 1/4" |
| H100-20 | 9/16"  | 1/4" |
| H100-30 | 9/16"  | 3/8" |
| H100-40 | 3/4"   | 3/8" |
| H100-50 | 7/8"   | 3/8" |
| H100-60 | 3/4"   | 1/2" |
| H100-70 | 7/8"   | 1/2" |
| H100-80 | 1 1/6" | 3/4" |

**TERMINALES MF JIC PARA PRENSAR**

|          |         |       |
|----------|---------|-------|
| H300-10  | 7/16"   | 1/4"  |
| H300-20  | 9/16"   | 1/4"  |
| H300-30  | 9/16"   | 3/8"  |
| H300-40  | 3/4"    | 3/8"  |
| H300-50  | 7/8"    | 3/8"  |
| H300-60  | 7/8"    | 1/2"  |
| H300-70  | 1 1/16" | 3/4"  |
| H300-80  | 1/2"    | 1/4"  |
| H300-90  | 9/16"   | 5/16" |
| H300-100 | 1 5/16" | 1"    |

**JIC HEMBRA GIRATORIO PARA PRENSAR**

|         |         |      |
|---------|---------|------|
| H500-10 | 9/16"   | 1/4" |
| H500-20 | 9/16"   | 3/8" |
| H500-30 | 3/4"    | 3/8" |
| H500-40 | 7/8"    | 3/8" |
| H500-50 | 7/8"    | 1/2" |
| H500-60 | 1 1/16" | 3/4" |
| H500-70 | 3/4"    | 1/4" |
| H500-80 | 3/4"    | 3/8" |
| H500-90 | 1 5/16" | 1"   |

**JIC HEMBRA GIRATORIO PARA PRENSAR 90°**


|          |       |       |
|----------|-------|-------|
| H600-100 | 1/4"  | 1/4"  |
| H600-200 | 5/16" | 5/16" |
| H600-300 | 3/8"  | 3/8"  |
| H600-400 | 1/2"  | 1/2"  |
| H600-500 | 5/8"  | 5/8"  |
| H600-600 | 3/4"  | 3/4"  |
| H600-700 | 1"    | 1"    |

**TERMINALES UNIÓN DOBLE PARA PRENSAR**


**ACCESORIOS**
**CÓDIGO**
**ROSCA**
**MANGUERA**


|          |             |  |
|----------|-------------|--|
| H700-100 | 7/16" UNF   |  |
| H700-200 | 9/16" UNF   |  |
| H700-300 | 3/4" UNF    |  |
| H700-400 | 7/8" UNF    |  |
| H700-500 | 1 1/16" UNF |  |
| H700-600 | 1 3/16" UNF |  |
| H700-700 | 1 5/16" UNF |  |

UNION DOBLE JIC X JIC



|         |          |  |
|---------|----------|--|
| N300-10 | 1/8" NPT |  |
| N300-20 | 1/4" NPT |  |
| N300-30 | 3/8" NPT |  |
| N300-40 | 1/2" NPT |  |
| N300-50 | 3/4" NPT |  |
| N300-60 | 1" NPT   |  |

ENTRE ROSCA NPT



|          |                         |  |
|----------|-------------------------|--|
| N400-10  | 7/16 x 1/8" JIC x NPT   |  |
| N400-20  | 9/16 x 1/8" JIC x NPT   |  |
| N400-30  | 7/16 x 1/4" JIC x NPT   |  |
| N400-40  | 9/16 x 1/4" JIC x NPT   |  |
| N400-50  | 3/4 x 1/4" JIC x NPT    |  |
| N400-60  | 9/16 x 3/8" JIC x NPT   |  |
| N400-70  | 3/4 x 3/8" JIC x NPT    |  |
| N400-80  | 7/8 x 3/8" JIC x NPT    |  |
| N400-90  | 3/4 x 1/2" JIC x NPT    |  |
| N400-100 | 7/8 x 1/2" JIC x NPT    |  |
| N400-110 | 1 1/16 x 1/2" JIC x NPT |  |
| N400-120 | 3/4 x 3/4" JIC x NPT    |  |
| N400-130 | 7/8 x 3/4" JIC x NPT    |  |
| N400-140 | 1 1/16 x 3/4" JIC x NPT |  |
| N400-150 | 1 3/16 x 3/4" JIC x NPT |  |
| N400-160 | 1 5/16 x 3/4" JIC x NPT |  |
| N400-170 | 1 5/16 x 1" JIC x NPT   |  |

CONECTOR RECTO JIC X NPT



|         |          |      |
|---------|----------|------|
| H800-10 | 1/4" BSP | 1/4" |
| H800-20 | 3/8" BSP | 1/4" |
| H800-30 | 1/4" BSP | 3/8" |
| H800-40 | 3/8" BSP | 3/8" |
| H800-50 | 1/2" BSP | 3/8" |
| H800-60 | 3/8" BSP | 1/2" |
| H800-70 | 1/2" BSP | 1/2" |
| H800-80 | 3/4" BSP | 3/4" |
| H800-90 | 1" BSP   | 1"   |

BSP HEMBRA GIRATORIO PARA PREISAR



|         |          |      |
|---------|----------|------|
| H900-10 | 1/4" BSP | 1/4" |
| H900-20 | 3/8" BSP | 1/4" |
| H900-30 | 1/4" BSP | 3/8" |
| H900-40 | 3/8" BSP | 3/8" |

BSP HEMBRA GIRATORIO PARA PREISAR 90°